

Connection for foul drainage
to existing manholes

Existing access
to be maintained

Existing Bitmac surface
maintained and improved

Turning
Area


Painted timber wheelie
bin enclosure

Existing access to be
retained


Parking for 2 no. cars
for Unit 1



Parking for 2 no. cars
for Unit 2



Turning
Area



Future
Housing

Existing Bitmac surface to be
removed and replaced with
gravel surface

Future
Housing

- E Parking bays revised Nov 16
- D Gated access reinstated, bin store moved, parking / turning revised Nov 16
- C Outbuilding included to form garage/store, ~~exc~~ and int rev'd Oct 16
- B Scheme amended to form two dwelling units Jun 16
- A Amenity areas added, Unit 4 removed Feb 16

HASTON REYNOLDS CHARTERED SURVEYORS 		DATE	Nov 2015	SCALE	1/200@A3	JOB TITLE	Mr D Briggs
		ORIGIN	ISR	VERIFIED	ISR	FILE NAME	SambrookHallFarm
		ISSUE					
		FILE NAME	SambrookBarrnPropP1b				
+44 (0) 1902 84 05 48 ian@hastonreynolds.co.uk							
DRAWING TITLE Site Layout		DWG NO H0013-03-A3-PL-03					